Service Bulletin No. 0006

Subject

New Veronte Autopilot 1x firmware, release 6.12.116-RTM.

Compliance Consideration

Embention considers this Service Bulletin as mandatory.

Models affected

All Veronte Autopilots running any firmware release in 6.12 and prior to revision 6.12.116.

Effectivity date

22/10/2024

Compliance time

This Service Bulletin is recommended at the next scheduled maintenance event.

Purpose

Veronte Autopilot 1x firmware update to release 6.12.116-RTM.

Release Notes: 6.12.112 → 6.12.116

Changed:

- Now the CAN bus terminal resistors are enabled by default in the AP0 of the 4xVeronte for HW versions higher than or equal to 4.8.

Instructions

Firmware update instructions can be found at https://manuals.embention.com/veronte-updater/en/latest/index.html

F.556.01

Material required

- Veronte Autopilot 1x firmware release 6.12.116-RTM, available at the Joint Collaboration Framework.
- Veronte Tools last package, available at the Joint Collaboration Framework.

Note

Go to https://manuals.embention.com/joint-collaboration-framework/en/0.1/releases/index.html for help finding the latest software versions at the Joint Collaboration Framework.